

Message

---

**From:** Fennessy, Christopher [christopher.fennessy@Rocket.com]  
**Sent:** 6/28/2017 6:04:00 PM  
**To:** MacNicholl, Peter@DTSC (Peter.MacNicholl@dtsc.ca.gov) (Peter.MacNicholl@dtsc.ca.gov)  
[Peter.MacNicholl@dtsc.ca.gov]; MacDonald, Alex@Waterboards (Alex.MacDonald@waterboards.ca.gov)  
[Alex.MacDonald@waterboards.ca.gov]; Keller, Lynn [Keller.Lynn@epa.gov]  
**Subject:** RAP Process  
**Attachments:** [EXTERNAL] FW: December 8 meeting follow-up; Scanned from a Xerox Multifunction Printer.pdf

Hi Peter – Attached (.pdf) is what Steve Ross provided in 2015 detailing the RAP process. May be helpful with your discussion with internal folks and review and edit of the schedule I provided.

Also, not sure it is completely helpful, but attached is an e-mail from Steve Ross regarding Charlie Ridenour's review of the original EPA letter regarding transitioning Area 40 to DTSC. Chris

**Christopher M. Fennessy, P.E.**  
**Aerojet Rocketdyne, Inc.**  
Engineering Manager, Site Remediation  
11260 Pyrites Way, Suite 125  
Rancho Cordova, CA 95670  
Ph: 916-355-3341  
Fax: 916-355-6145  
Email: [Christopher.Fennessy@Rocket.com](mailto:Christopher.Fennessy@Rocket.com)